

Type	L #	Hits	Search Text	DBs	Time Stamp	Comments
1	BRS	L2	3	"2001/017775" "090957"	US -PGPUB; EPO; DERWENT; IBM _TDB	2005/11/30 13:35
2	BRS	L4	27	reinert.in.	US -PGPUB	2005/11/30 13:36
3	BRS	L5	1	(road with (marker marking)) and (light reflecting) and (electrical with (conductor conducting)) and (cable with duct)	US -PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM _TDB	2005/11/30 14:54
4	BRS	L6	10	"1011959".pn. "1010491".pn.	EPO; DERWENT; IBM _TDB	2005/11/30 14:13
5	BRS	L7	12	"9900680"	EPO; DERWENT; IBM _TDB	2005/11/30 14:42
6	BRS	L9	244	((roadway road) and (marker marking)) and (LED illuminat\$ bulb light lighting reflector reflecting) and (electrical with (conductor conducting)) and (cable)	US -PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM _TDB	2005/11/30 14:57

Type	L #	Hits	Search Text	DBs	Time Stamp	Comments
7	BRS	L10 34	((roadway road) with (marker marking) and (LED illuminat\$ bulb light lighting reflector reflecting) and (electrical with (conductor conducting)) and (cable)	US - PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2005/11/30 14:57	

Error Definition	Errors
	7

Type	Hits	Search Text	DBs	Time Stamp
1	BRS 6	"404"/\$.cc1s. and (road with (marker marking)) and (light lighting reflector reflecting) and (electrical with (conductor conducting))	US_PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2005/11/30 13:37
2	BRS 30	"2001017775" "1006641" "90957"	US_PGPUB; EPO; DERWENT; IBM_TDB	2005/11/30 13:35